REPORT OF SCHOOL BUS INSPECTION

Type of Annual Time: Date: 1/26/2016 1:43 PM Inspection: Name of School Corporation: CROSSING EDUCATIONAL CENTER Corp ID: 20A991 **Address of School Corporation:** 2930 S. Napanee St. County City: Elkhart Zip: 46517 20 Number: License VIN: 4UZAAXBV03CK90726 B246H **Bus Number:** 2 Number: Make of Blue Bird Make of Body: Freightliner Year: 2003 Year: 2003 Chassis: Corporation **Bus Type:** С Mileage: 141401 Inspected PE: 5506 **Inspection Status:** O Brian Bills By:

Violations - Rejected

Inspection Code	<u>Description</u>
26-1-2	Not fully charged
/ M_ I _ /	Outside exit not outlined with yellow or white 1" in width reflective tape(after chassis manufactured date of 05-02-94)
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	<u>Description</u>
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.