

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	2/2/2016	Time:	1:33 PM
Name of School Corporation:	CENTRAL CATHOLIC HIGH SCHOOL			Corp ID:	79D415
Address of School Corporation:	2410 S 9th St				
City:	Lafayette	Zip:	47905	County Number:	79
VIN:	4DRBWAAR8DB335698			Bus Number:	2
Make of Body:	IC Corporation	Year:	2013	Make of Chassis:	IC Corporation
Bus Type:	D			Year:	2013
Inspection Status:	O	Inspected By:	Nate King	PE:	7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-4	Stop arm does not function properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.