

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/3/2016	Time:	4:24 PM
Name of School Corporation:	STUDENT TRANSIT - RICHMOND	Corp ID:	89001Z		
Address of School Corporation:	3175 Salisbury Rd N				
City:	Richmond	Zip:	47374	County Number:	89
VIN:	4UZABRDT7FCGH7989	License Number:	7864	Bus Number:	89
Make of Body:	Thomas Built Buses, Inc.	Year:	2014	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	23078		
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.