

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 2/17/2016 **Time:** 9:20 AM
Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS **Corp ID:** 475075
Address of School Corporation: 595 Stars Blvd
City: Bedford **Zip:** 47421 **County Number:** 47
VIN: 4DRBRAAN54B962945 **License Number:** 19552 **Bus Number:** A24
Make of Body: IC Corporation **Year:** 2004 **Make of Chassis:** IC Corporation **Year:** 2004
Bus Type: C **Mileage:** 143783
Inspection Status: O **Inspected By:** Travis Coryea **PE:** 5892

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 29-1-2 | Floor covering is missing, cut, loose, buckled, bulging, or not secure |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.