REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Post-Crash InspectionDate:2/22/2016Time:8:34 AMName of School Corporation:DELAWARE COMM. SCHOOL CORP.Corp ID:181875

Address of School Corporation: 7821 SR 3 N

City:MuncieZip:47303County Number:18VIN:4DRBUAAN7DB311038License Number:4851Bus Number:1221Make of Body:IC Corporation Year:2013Make of Chassis:IC Corporation Year:2013

Bus Type: C Mileage: 54677

Inspection Status: A Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.