REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/22/2016Time:9:50 AMName of School Corporation:DELAWARE COMM. SCHOOL CORP.Corp ID:181875

Address of School Corporation: 7821 SR 3 N

City:MuncieZip:47303County Number:18VIN:4DRAPSKH7CB591740License Number:5559Bus Number:3Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2012

Bus Type: Mileage: 30860

Inspection Status: A Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description