

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 2/26/2016 **Time:** 10:27 AM
Name of School Corporation: SOUTH DEARBORN COMM. SCH. CORP **Corp ID:** 151600
Address of School Corporation: 6109 Squire Place
City: Aurora **Zip:** 47001 **County Number:** 15
VIN: 4drbuaap9cb665160 **License Number:** 2735 **Bus Number:** 48
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2012
Bus Type: C **Mileage:** 22600
Inspection Status: R **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.