

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 3/9/2016      **Time:** 9:53 AM  
**Name of School Corporation:** EAST GIBSON SCHOOL CORPORATION      **Corp ID:** 262725  
**Address of School Corporation:** 941 S Franklin St  
**City:** Oakland City      **Zip:** 47660      **County Number:** 26  
**VIN:** 1GB6G3AG8A1145550      **License Number:** 2370      **Bus Number:** 21  
**Make of Body:** Star Trans      **Year:** 2010      **Make of Chassis:** Chevrolet      **Year:** 2010  
**Bus Type:**      **Mileage:** 42959  
**Inspection Status:** A      **Inspected By:** Bradley Miller      **PE:** 7809

### Violations - Rejected

### Inspection Code Description

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description