

# REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 3/9/2016 **Time:** 10:11 AM  
**Name of School Corporation:** EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725  
**Address of School Corporation:** 941 S Franklin St  
**City:** Oakland City **Zip:** 47660 **County Number:** 26  
**VIN:** 1GB6G3AG8A1165037 **License Number:** 2369 **Bus Number:** 22  
**Make of Body:** Star Trans **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010  
**Bus Type:** **Mileage:** 48849  
**Inspection Status:**  **Inspected By:** Bradley Miller **PE:** 7809

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

## Violations - Out of Service

Inspection Code Description

Bus Type Description