REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	3/9/2016	**Time:**	10:11 AM
Name of School Corporation:	EAST GIBSON SCHOOL CORPORATION				**Corp ID:**	262725
Address of School Corporation:	941 S Franklin St					
City:	Oakland City	**Zip:**	47660		**County Number:**	26
VIN:	1GB6G3AG8A1165037		**License Number:**	2369	**Bus Number:**	22
Make of Body:	Star Trans **Year:**	2010	**Make of Chassis:**	Chevrolet	**Year:**	2010
Bus Type:			**Mileage:**	48849		
Inspection Status:	O	**Inspected By:**	Bradley MIller		**PE:**	7809

Violations - Rejected

Inspection Code	Description
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code	Description

Bus Type Description