## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:3/11/2016Time:8:15 AMName of School Corporation:NORTH LAWRENCE COMM. SCHOOLSCorp ID:475075

Address of School Corporation: 595 Stars Blvd

City:BedfordZip:47421County Number:47VIN:1HVBBABN2YH304083License Number:17605Bus Number:A14Make of Body:AmTranYear:2000Make of Chassis:IC CorporationYear:2000

Bus Type: C Mileage: 106427

Inspection Status: R Inspected By: Travis Coryea PE: 5892

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

Any lens is cracked, broken or discolored
The stop arm has faded or lost reflectivity

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.