

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	Date:	3/11/2016	Time:	11:30 AM		
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300		
Address of School Corporation:	5808 E Administration Rd						
City:	Marengo	Zip:	47140	County Number:	13		
VIN:	1BAAHCPh73F208768		License Number:	B523D	Bus Number:	32	
Make of Body:	Blue Bird Corporation	Year:	2003	Make of Chassis:	Blue Bird Corporation	Year:	2003
Bus Type:	D			Mileage:	134146		
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-2	Any seat back or bottom is loose
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.