

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/16/2016	Time:	9:04 AM		
Name of School Corporation:	SCHOOL TOWN OF MUNSTER			Corp ID:	454740		
Address of School Corporation:	8616 Columbia Ave						
City:	Munster	Zip:	46321	County Number:	45		
VIN:	4DRBWAAN69A042327		License Number:	32437	Bus Number:	35	
Make of Body:	IC Corporation	Year:	2009	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	D			Mileage:	63079		
Inspection Status:	O	Inspected By:	Dale Morgan	PE:	4743		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly
59-1-7	Any optional rear stop arm device or school bus crossing arm criteria is not met
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
51-2-1	The service door does not open or close properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.