REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/16/2016	**Time:**	10:36 AM
Name of School Corporation:	PRIMROSE SCHOOL @ GRAY EAGLE			**Corp ID:**	290003
Address of School Corporation:	12290 Olio Rd.				
City:	Fishers	**Zip:**	46037	**County Number:**	29
VIN:	1GBHG31V261253225	**License Number:**	B782AB	**Bus Number:**	1
Make of Body:	Chevrolet **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2006
Bus Type:	A1	**Mileage:**	19793		
Inspection Status:	R	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
62-1-2	One (1) taillight or one (1) brake light does not function
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**