REPORT OF SCHOOL BUS INSPECTION

Type of Time: 11:05 AM Post-Crash Inspection Date: 3/21/2016 Inspection: Name of School Corporation: **GRIFFITH PUBLIC SCHOOLS** Corp ID: 454700 Address of School Corporation: 602 N Raymond City: Griffith Zip: 46319 **County Number: 45** VIN: 4drbuc8n3fb653588 License Number: 8467 **Bus Number:** Make of Body: IC Corporation Year: 2015 Make of Chassis: IC Corporation Year: 2015 **Bus Type:** Mileage: 17416

Inspected By: Nathan Sherer

PE:

7029

Violations - Rejected

Inspection Status: O

Inspection Code	<u>Description</u>
51-1-1	Any door seals are missing, damaged, or torn
25-1-2	Mirrors do not meet minimum specifications for indirect visibility as set out in Indiana's minimum specifications for school buses
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
90-1-3	The strobe light is inoperative
20-1-5	Door glass is chipped, or cracked
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	<u>Description</u>
25-2-2	Reflective glass is cracked, broken, or missing
59-2-1	Any stop arm light is inoperative
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
69-2-1	Wipers fail to function

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.