## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:3/21/2016Time:9:30 AMName of School Corporation:NORTH LAWRENCE COMM. SCHOOLSCorp ID:475075

Address of School Corporation: 595 Stars Blvd

City: Bedford Zip: 47421 County Number: 47

VIN: 1HVBBABN4YH304084 License Number: 17606 Bus Number: A36

Make of Body: AmTran Year: 2000 Make of Chassis: IC Corporation Year: 2000

Bus Type: C Mileage: 107274

Inspection Status: O Inspected By: Travis Coryea PE: 5892

**Violations - Rejected** 

**Inspection Code Description** 

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.