

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/22/2016	Time:	1:20 PM		
Name of School Corporation:	LAKE CENTRAL SCHOOL CORP.			Corp ID:	454615		
Address of School Corporation:	8855 Wicker Ave						
City:	St John	Zip:	46373	County Number:	45		
VIN:	4DRBUAFN98B556809		License Number:	31275	Bus Number:	66	
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	C			Mileage:	160100		
Inspection Status:	R	Inspected By:	Dale Morgan	PE:	4743		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.