

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 3/22/2016	Time: 9:50 AM
Name of School Corporation: JENNINGS COUNTY SCHOOL CORP.	Corp ID: 404015	
Address of School Corporation: 34 Main St		
City: North Vernon	Zip: 47265	County Number: 40
VIN: 4DRBUAAN2EB791135	License Number: 6513	Bus Number: C134
Make of Body: IC Corporation	Year: 2014	Make of Chassis: IC Corporation
Year: 2014	Mileage: 44542	Year: 2014
Bus Type: C		
Inspection Status: O	Inspected By: Chris Clark	PE: 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.