

## REPORT OF SCHOOL BUS INSPECTION

|                                |                              |                 |            |                  |                          |       |      |
|--------------------------------|------------------------------|-----------------|------------|------------------|--------------------------|-------|------|
| Type of Inspection:            | Annual                       | Date:           | 3/29/2016  | Time:            | 9:08 AM                  |       |      |
| Name of School Corporation:    | PAOLI COMMUNITY SCHOOL CORP. |                 |            | Corp ID:         | 596155                   |       |      |
| Address of School Corporation: | 501 S Elm St                 |                 |            |                  |                          |       |      |
| City:                          | Paoli                        | Zip:            | 47454      | County Number:   | 59                       |       |      |
| VIN:                           | 4UZABRDU3ACAN7520            | License Number: | 33060      | Bus Number:      | P12                      |       |      |
| Make of Body:                  | Thomas Built Buses, Inc.     | Year:           | 2010       | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2010 |
| Bus Type:                      | C                            | Mileage:        | 73689      |                  |                          |       |      |
| Inspection Status:             | R                            | Inspected By:   | Mike Adams | PE:              | 7407                     |       |      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                 |
|------------------------|----------------------------------------------------------------------------------------------------|
| 29-1-2                 | Floor covering is missing, cut, loose, buckled, bulging, or not secure                             |
| 63-1-3                 | Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves |

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.