REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:3/29/2016Time:9:21 AMName of School Corporation:SOUTH GIBSON SCHOOL CORP.Corp ID:262765

Address of School Corporation: 1029 W 650 S

City:Fort BranchZip:47648County Number:26VIN:4DRBUAAN9CB615857License Number:Bus Number:8Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2012

Bus Type: C Mileage: 51418

Inspection Status: R Inspected By: Bradley Miller PE: 7809

Violations - Rejected

Inspection Code Description

46-1-2 Any seat back or bottom is loose

The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2

28-1-4 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.