REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	: Annual		Date:	3/31/2016	Time:	9:42 AM
Name of School Co	orporation: CUL	/ER EDUCATIO	NAL FOUNDATION	1	Corp ID:	50001Z
Address of School	Corporation:	1300 Academy	/ Rd 154			
City:	Culver	Zip:	46511		County Number:	50
VIN:	4UZABRDT4FC	G9526	License Number:	B724J	Bus Number:	3
Make of Body:	Freightliner Year:	2014	Make of Chassis:	Freightliner	Year:	2014
Bus Type:	С		Mileage:	20565		
Inspection Status:	А	Inspected By:	Travis Harrold		PE:	8022

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.