REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	4/7/2016	**Time:**	7:47 AM
Name of School Corporation:	HANOVER COMM. SCHOOL CORP.				**Corp ID:**	454580
Address of School Corporation:	PO Box 645					
City:	Cedar Lake	**Zip:**	46303		**County Number:**	45
VIN:	1GB3G2BG1C1196659		**License Number:**	14188	**Bus Number:**	44
Make of Body:	Star Trans	**Year:** 2012	**Make of Chassis:**	Chevrolet	**Year:**	2012
Bus Type:			**Mileage:**	43110		
Inspection Status:	R	**Inspected By:**	Dale Morgan		**PE:**	4743

Violations - Rejected

Inspection Code	Description
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code	Description

Bus Type Description