REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual			Date:	4/7/2016	Time:	9:17 AM
Name of School Corporation: HAN		OVER COMM. S	SCHOOL CORP.		Corp ID:	454580
Address of School Corporation:		PO Box 645				
City:	Cedar Lake	Zip:	46303		County Number:	45
VIN:	4drbuskn3cb446696		License Number:	627	Bus Number:	4
Make of Body:	IC Corporation Year:	2012	Make of Chassis:	IC Corporation	Year:	2012
Bus Type:	С		Mileage:	59851		
Inspection Status:	0	Inspected By:	Dale Morgan		PE:	4743

Violations - Rejected

Inspection CodeDescription23-1-5Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection CodeDescription59-2-3Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.