

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/11/2016	<b>Time:</b>	8:12 AM
<b>Name of School Corporation:</b>	NORTH JUDSON-SAN PIERRE SCH CO			<b>Corp ID:</b>	757515
<b>Address of School Corporation:</b>	801 Campbell Dr				
<b>City:</b>	North Judson	<b>Zip:</b>	46366	<b>County Number:</b>	75
<b>VIN:</b>	1BAKGCPH5DF291755	<b>License Number:</b>	D032788	<b>Bus Number:</b>	12
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2013	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	39760	<b>Year:</b>	2013
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Dale Morgan	<b>PE:</b>	4743

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
3-1-3	Any battery is loose in its mounting.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**