

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                             |                        |             |                         |              |              |      |
|---------------------------------------|-----------------------------|------------------------|-------------|-------------------------|--------------|--------------|------|
| <b>Type of Inspection:</b>            | Annual                      | <b>Date:</b>           | 4/14/2016   | <b>Time:</b>            | 8:53 AM      |              |      |
| <b>Name of School Corporation:</b>    | KANKAKEE VALLEY SCHOOL CORP |                        |             | <b>Corp ID:</b>         | 373785       |              |      |
| <b>Address of School Corporation:</b> | PO Box 278                  |                        |             |                         |              |              |      |
| <b>City:</b>                          | Wheatfield                  | <b>Zip:</b>            | 46392       | <b>County Number:</b>   | 37           |              |      |
| <b>VIN:</b>                           | 4UZAAXCT46CV43435           | <b>License Number:</b> | 21015       | <b>Bus Number:</b>      | 4            |              |      |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.    | <b>Year:</b>           | 2006        | <b>Make of Chassis:</b> | Freightliner | <b>Year:</b> | 2006 |
| <b>Bus Type:</b>                      | B                           | <b>Mileage:</b>        | 157221      |                         |              |              |      |
| <b>Inspection Status:</b>             | A                           | <b>Inspected By:</b>   | Dale Morgan | <b>PE:</b>              | 4743         |              |      |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.