## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection **Date:** 4/14/2016 **Time:** 10:37 AM **Name of School Corporation:** EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1165037License Number:2369Bus Number:22Make of Body:Star Trans Year:2010Make of Chassis:Chevrolet Year:2010

Bus Type: Mileage: 49158

Inspection Status: A Inspected By: Bradley Miller PE: 7809

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**