

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/14/2016	<b>Time:</b>	10:08 AM
<b>Name of School Corporation:</b>	PERU COMMUNITY SCHOOLS	<b>Corp ID:</b>	525635		
<b>Address of School Corporation:</b>	35 W 3rd St				
<b>City:</b>	Peru	<b>Zip:</b>	46970	<b>County Number:</b>	52
<b>VIN:</b>	1GB6G5BGXF1102054	<b>License Number:</b>	31241	<b>Bus Number:</b>	Tiger3
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2015	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2015	<b>Year:</b>	2015	<b>Year:</b>	2015
<b>Bus Type:</b>	A2	<b>Mileage:</b>	21884		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded

### Violations - Out of Service

Inspection Code   Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.