

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/14/2016	Time: 10:19 AM
Name of School Corporation: PERU COMMUNITY SCHOOLS	Corp ID: 525635	
Address of School Corporation: 35 W 3rd St		
City: Peru	Zip: 46970	County Number: 52
VIN: 4UZABRDJ79CAD3296	License Number: 32093	Bus Number: 3
Make of Body: Thomas Built Buses, Inc.	Year: 2009	Make of Chassis: Freightliner
Year: 2009	Mileage: 106255	Year: 2009
Bus Type: C		
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.