

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/14/2016 Time: 11:19 AM
Name of School Corporation: PERU COMMUNITY SCHOOLS Corp ID: 525635
Address of School Corporation: 35 W 3rd St
City: Peru Zip: 46970 County Number: 52
VIN: 1GB6G3AGXA1168294 License Number: 83999 Bus Number: Tiger2
Make of Body: Starcraft Year: 2010 Make of Chassis: Chevrolet Year: 2010
Bus Type: A2 Mileage: 57758
Inspection Status: R Inspected By: Randy McPike PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-1	Any seat is loose from the floor or seat rail
20-1-2	Excessive effort is needed to open the emergency door
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.