

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks **Date:** 4/18/2016 **Time:** 9:22 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP **Corp ID:** 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo **Zip:** 47140 **County Number:** 13
VIN: 1GBL7T1C9XJ106717 **License Number:** B287f **Bus Number:** 31
Make of Body: Chevrolet **Year:** 2000 **Make of Chassis:** Chevrolet **Year:** 2000
Bus Type: C **Mileage:** 192851
Inspection Status: O **Inspected By:** Travis Coryea **PE:** 5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-5	There is brake fluid leaking at any point

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.