

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/18/2016	Time:	10:26 AM		
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300		
Address of School Corporation:	5808 E Administration Rd						
City:	Marengo	Zip:	47140	County Number:	13		
VIN:	1HVBBAAP0XH232236	License Number:	B331G	Bus Number:	33		
Make of Body:	IC Corporation	Year:	1999	Make of Chassis:	IC Corporation	Year:	1999
Bus Type:	C	Mileage:	135472				
Inspection Status:	R	Inspected By:	Travis Coryea	PE:	5892		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.