

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	4/19/2016	<b>Time:</b>	1:26 PM
<b>Name of School Corporation:</b>	WHITKO COMMUNITY SCHOOL CORP.	<b>Corp ID:</b>	434455		
<b>Address of School Corporation:</b>	PO Box 114				
<b>City:</b>	Pierceton	<b>Zip:</b>	46562	<b>County Number:</b>	92
<b>VIN:</b>	1GB3G3BG4B1111124	<b>License Number:</b>	3911	<b>Bus Number:</b>	W1
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2011	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2011	<b>Mileage:</b>	120540	<b>PE:</b>	5506
<b>Bus Type:</b>	B	<b>Inspected By:</b>	Brian Bills		
<b>Inspection Status:</b>	A				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**