

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 4/20/2016 **Time:** 7:47 AM
Name of School Corporation: HANOVER COMM. SCHOOL CORP. **Corp ID:** 454580
Address of School Corporation: PO Box 645
City: Cedar Lake **Zip:** 46303 **County Number:** 45
VIN: 1GB3G2BG1C1196659 **License Number:** 14188 **Bus Number:** 44
Make of Body: Star Trans **Year:** 2012 **Make of Chassis:** Chevrolet **Year:** 2012
Bus Type: **Mileage:** 43110
Inspection Status: A **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description