## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	4/20/2016	Time:	10:42 AM
Name of School	•			OL CORP.	Corp ID:	686805
Address of School Corporation:		One Rebe	I Dr		County	
City:	Lynn	Zip:	47355		Number:	68
VIN:	1BAKGCPH5BF278730		License Number:	74831	Bus Number:	4
Make of Body:	Blue Bird Corporation	Year: 2011	Make of Chassis:	Blue Bird Corporation	Year:	2011
Bus Type:	С		Mileage:	64596		
Inspection Status:	0	Inspected By:	Jamie Hotchk	iss	PE:	6458

## **Violations - Rejected**

Inspection Code	Description
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

## **Violations - Out of Service**

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.