## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	4/26/2016	Time:	9:45 AM
Name of School Corporation: BLUE RIVER SERVICESCorp ID:450						450001
Address of School	Corporation:	3141 Progress	Blvd.			
City:	Corydon	Zip:	47112		<b>County Number:</b>	31
VIN:	1GBJG31U3611	88250	License Number:	21080	Bus Number:	99
Make of Body:	Chevrolet Year:	2006	Make of Chassis:	Chevrolet	Year:	2006
Bus Type:	A2		Mileage:	176704		
Inspection Status:	0	Inspected By:	Troy Boyd		PE:	5171

**Violations - Rejected** 

Inspection CodeDescription2-1-1Required back-up lights do not function.

## **Violations - Out of Service**

Inspection Code Description

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.