

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/28/2016	Time:	8:34 AM		
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300		
Address of School Corporation:	5808 E Administration Rd						
City:	Marengo	Zip:	47140	County Number:	13		
VIN:	4DRBUSKP5BB266216		License Number:	2537	Bus Number:	50	
Make of Body:	IC Corporation	Year:	2011	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	C			Mileage:	56094		
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.