REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	4/28/2016	Time:	9:31 AM
Name of School Address of Sch	l Corporation: Cl		COMM. SCHOC)L CORP	Corp ID:	131300
City:	Marengo	Zip:	47140		County Number:	13
VIN:	4UZABRDU3ACAN3189		License Number:	75141	Bus Number:	52
Make of Body:	Thomas Built Buses, Ye Inc.	ear: 2010	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2010
Bus Type:	С		Mileage:	57858		
Inspection Status:	R	Inspected By:	Travis Coryea		PE:	5892

Violations - Rejected

Inspection Code	<u>Description</u>
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs,

carpets, mats, etc.)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.