

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/6/2016	Time:	9:51 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.	Corp ID:	525625		
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	4UZABRCS17CY17482	License Number:	4447	Bus Number:	21
Make of Body:	Thomas Built Buses, Inc.	Year:	2007	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	136312		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.