

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/6/2016	<b>Time:</b> 10:44 AM
<b>Name of School Corporation:</b> OAK HILL UNITED SCHOOL CORP.	<b>Corp ID:</b> 525625	
<b>Address of School Corporation:</b> PO Box 550		
<b>City:</b> Converse	<b>Zip:</b> 46919	<b>County Number:</b> 52
<b>VIN:</b> 1GBJG31UX61211085	<b>License Number:</b> 76867	<b>Bus Number:</b> 2SAV
<b>Make of Body:</b> Mid Bus, Inc. <b>Year:</b> 2006	<b>Make of Chassis:</b> Mid Bus, Inc. <b>Year:</b> 2006	
<b>Bus Type:</b> A2	<b>Mileage:</b> 74257	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Randy McPike	<b>PE:</b> 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
20-1-6	Required padding is missing

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.