

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/6/2016	Time:	10:44 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	1GBJG31UX61211085		License Number:	76867	Bus Number:	2SAV	
Make of Body:	Mid Bus, Inc.	Year:	2006	Make of Chassis:	Mid Bus, Inc.	Year:	2006
Bus Type:	A2		Mileage:	74257			
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
20-1-6	Required padding is missing

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

## Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.