

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/9/2016	Time: 11:27 AM
Name of School Corporation: KOKOMO SCHOOL CORPORATION	Corp ID: 343500	
Address of School Corporation: 620 W Deffenbaugh		
City: Kokomo	Zip: 46901	County Number: 34
VIN: 4DRBVAAR67A387022	License Number: 21690	Bus Number: 107
Make of Body: IC Corporation	Year: 2007	Make of Chassis: IC Corporation
Year: 2007	Mileage: 100552	PE: 7018
Bus Type: D		
Inspection Status: O	Inspected By: Randy McPike	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
59-1-9	There is air leak at the stop arm air bladder that does not affect the air braking system
59-1-1	The stop arm lights do not flash alternately
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.