REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	5/9/2016	**Time:**	9:04 AM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP				**Corp ID:**	131300
Address of School Corporation:	5808 E Administration Rd					
City:	Marengo	**Zip:**	47140		**County Number:**	13
VIN:	1GBJG31U741225197		**License Number:**	Temp	**Bus Number:**	40
Make of Body:	Mid Bus, Inc.	**Year:** 2004	**Make of Chassis:**	Chevrolet	**Year:**	2004
Bus Type:	A2		**Mileage:**	147464		
Inspection Status:	O	**Inspected By:**	Travis Coryea		**PE:**	5892

Violations - Rejected

Inspection Code	Description
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code	Description
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**