## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/9/2016Time:10:03 AMName of School Corporation: CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1GB3G2BGXC1107641License Number:C758000Bus Number:87Make of Body:Chevrolet Year:2012Make of Chassis:Chevrolet Year:2012

Bus Type: Mileage: 89582

Inspection Status: R Inspected By: Travis Coryea PE: 5892

Violations - Rejected

20-1-8 If bus manufactured after 5-2-1994, positive door opening device is missing or fails to

operate properly

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**