REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | : Annual | | Date: | 5/12/2016 | Time: | 9:14 AM |
|-----------------------------|---------------------|---------------|------------------|----------------|----------------|---------|
| Name of School Corporation: | | ROCK-HAWCF | REEK SCHOOL CO | RP | Corp ID: | 30370 |
| Address of School | Corporation: | 9423 N SR 9 | | | | |
| City: | Норе | Zip: | 47246 | | County Number: | 3 |
| VIN: | 4DRBUAANXNB690 | 379 | License Number: | 31718 | Bus Number: | 20 |
| Make of Body: | IC Corporation Year | 2009 | Make of Chassis: | IC Corporation | Year: | 2009 |
| Bus Type: | В | | Mileage: | 101366 | | |
| Inspection Status: | R | Inspected By: | Travis Coryea | | PE: | 5892 |

Violations - Rejected

| Inspection <u>Code</u> | Description |
|---------------------------|--|
| 65-1-1 | Any lens is cracked, broken or discolored |
| 20-1-8 | If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.