REPORT OF SCHOOL BUS INSPECTION

Type of Annual 5/25/2016 Time: 10:29 AM Date: Inspection:

Name of School Corporation: TRI-COUNTY SCHOOL CORPORATION Corp ID: 918535

Address of School Corporation:

County Number: 91 City: Zip: VIN: 4DRBUSKN7CB591059 License Number: B971F **Bus Number:**

IC Make of Body: **Year:** 2012 Make of Chassis: IC Corporation Year: 2012 Corporation

Bus Type: Mileage: 58890

Inspection Status: O Inspected By: Nate King PE: 7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Description Code

Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent 63-2-5

major grooves

Bus Type Description