

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/1/2016	<b>Time:</b> 10:55 AM
<b>Name of School Corporation:</b> YORKTOWN COMMUNITY SCHOOLS	<b>Corp ID:</b> 181910	
<b>Address of School Corporation:</b> 8800 W Smith St		
<b>City:</b> Yorktown	<b>Zip:</b> 47396	<b>County Number:</b> 18
<b>VIN:</b> 1BAKJCPA5BF278649	<b>License Number:</b> 338	<b>Bus Number:</b> 16
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2011	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2011	<b>Year:</b> 2011	
<b>Bus Type:</b> C	<b>Mileage:</b> 26754	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jamie Hotchkiss	<b>PE:</b> 6458

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**