

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/1/2016	Time: 9:34 AM
Name of School Corporation: LANESVILLE COMMUNITY SCH. CORP	Corp ID: 313160	
Address of School Corporation: 2725 Crestview Ave NE		
City: Lanesville	Zip: 47136	County Number: 31
VIN: 4DRBWAAR27A390559	License Number: 30109	Bus Number: 12
Make of Body: IC Corporation	Year: 2007	Make of Chassis: IC Corporation
Year: 2007	Mileage: 97590	Year: 2007
Bus Type: D		
Inspection Status: O	Inspected By: Troy Boyd	PE: 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
46-1-2	Any seat back or bottom is loose

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.