

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 6/3/2016      **Time:** 8:03 AM  
**Name of School Corporation:** SOUTH NEWTON SCHOOL CORP.      **Corp ID:** 565995  
**Address of School Corporation:** 13232 S 50 E  
**City:** Kentland      **Zip:** 47951      **County Number:** 56  
**VIN:** 1GB6G2AG2A1133713      **License Number:** 83265      **Bus Number:** 2M  
**Make of Body:** Chevrolet      **Year:** 2010      **Make of Chassis:** Chevrolet      **Year:** 2010  
**Bus Type:**      **Mileage:** 64991  
**Inspection Status:** R      **Inspected By:** Nathan Sherer      **PE:** 7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------