## REPORT OF SCHOOL BUS INSPECTION

Type of 10:46 Time: Annual Date: 6/8/2016 Inspection: AM Name of School Corporation: CULVER COMMUNITY SCHOOLS CORP. Corp ID: 505455 **Address of School Corporation:** PO Box 231 County City: Culver Zip: 46511 50 Number: License VIN: 4DRBYAFP96A236026 2490 **Bus Number:** 05 Number: Make of IC Blue Bird Year: 2006 2006 Make of Body: Year: Corporation Corporation Chassis: **Bus Type:** С Mileage: 62690 Inspection Inspected 0 PE: Travis Harrold 8022 Status: By:

### **Violations - Rejected**

# <u>Inspection Code</u> <u>Description</u>

23-1-5 Any hanger, clamp or bracket is missing, loose or broken

#### **Violations - Out of Service**

Inspection Code Description

69-2-1 Wipers fail to function

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.