## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual			Date:	6/8/2016	Time:	10:58 AM
Name of School Co	orporation:	CULV	ER COMMUNI	TY SCHOOLS COR	P.	Corp ID:	505455
Address of School	Corporation:		PO Box 231				
City:	Culver		Zip:	46511		<b>County Number:</b>	50
VIN:	4DRBUAFP98	B5568	13	License Number:	12674	Bus Number:	30
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	С			Mileage:	130987		
Inspection Status:	0		Inspected By:	Travis Harrold		PE:	8022

**Violations - Rejected** 

Inspection Code Description

**Violations - Out of Service** 

Inspection CodeDescription64-2-1Any rear turn signal does not function properly

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.